


2018 MAZDA CX-8 2.2 XD L Package PROACTIVE Diesel Turbo 4WD		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-KG2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/11	MILEAGE 65,000 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. KG2P-201294	DIMENSIONS (L X W X H) 490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Side Camera Adaptive Cruise Control 360° Camera		Leather Seats Pre-Collision Braking Back Camera Front Camera Navigation System	
INSPECTOR REPORT			
Front glass: Scratches, stone chips, cracks, repair marks, needs replacement. Interior: Scratches, dirt, burn holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成30年 11月		車名・グレード CX-8 XD Lパッケージ		2WD (4WD)		評価点 (4.5)	
ディーラー・並行 モデル年式 年 ハンドル 左・右		型式 3DA-KG2P		排気量 2200	ドア 5	定員 7人	外装 内装 B B
車種 自家用		シフト FAT		セールスポイント (正常に機能するものに限りです)			
車検 令和9年 11月 (日)		冷房 WAC		BOSEサウンドシステム・マツダコネクナビ			
走行 6万4千510 km		燃料 軽油		360° ビューカメラ・BSM・ステアリングヒーター			
色 ブラック		色コード 41W		シートヒーター・レーダークルーズ・パワーバックドア			
R券 13,480 円				装備品 (純正品に限り○をつけてください)			
注意事項申告欄				(PS) (PW) (ABS) (ESP) (AW) SR (ナビ) (TV) (カメラ)			
外装 小A・小U				新車保証書 後日品			
室内 汚れ				有・無			
フロントガラス キズ・破り・ヒビ割・リペア跡・X要 内装 キズ・破り・コゲ・穴・スレ・キレ・破れ							
車台番号 201294				A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済			
登録番号 名変中				型式指定番号 登録区分番号 車検有効期 年 月 日 備考			