

2018 MAZDA CX-8 2.2 XD PROACTIVE Diesel Turbo		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE 3DA-KG2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/07	MILEAGE 62,261 km		
DOORS 5	SEATS 7		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Pearl White		
BODY TYPE SUV			
CHASSIS NO. KG2P-122248	DIMENSIONS (L X W X H) 490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels Side Camera		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Front glass: scratches, stone chips, cracks, repair marks, replacement/repair needed. Interior: scratches, dirt, burns, holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成30年 7月	車名・グレード CX-8 XD7° ロアクティブ°	(2WD) 4WD	評価点 (4)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 3DA-KG2P	排気量 2200 CC	ドア 5 形状 木
定員 7人	積載 kg	外装 C	内装 C
車歴 自家用	シフト FAT	セールスポイント (正常に機能するものに限りです)	
車検 令和9年 7月 (日)	冷房 WAC	キーレススマートキー☆ETC☆バックモニター	
走行 6万2千261 km	燃料 軽油	装備品 (純正品に限り○をつけてください)	
色 パール	色替 色コード 711	(PS) SR	(PW) ナビ
R券 12,860 円		(BS) TV	(AB) カワ
注意事項申告欄		AW	
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ	新車保証書 有・無	後日品
車台番号 122248		スベア	
登録番号 名変中		A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
		型式指定番号 シ-キ	識別区分番号 番 号
		車検取得月 年 月	車検 月 日