

2018 MAZDA CX-8 25S Proactive		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6BA-KG5P	DISPLACEMENT 2,488 cc		
YEAR / REG. 2018/11	MILEAGE 81,750 km		
DOORS 5	SEATS 6		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. KG5P-100846	DIMENSIONS (L X W X H) 490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Back Camera		Pre-Collision Braking Side Camera Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/11	メーカー マツダ	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4
車名 CX-8	グレード 25Sプロアクティブ	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 2500 cc	型式 6BA-KG5P	選装 型式	内装 A・B・C
車検 9年7月	抹消 燃料 ハイブリッド ()	ディーゼ ル	後付選用品 (保証書・取扱説明書 等)	
走行 81,750 km	マイル AT	シフト		
外装色 スノープレイクホワイトパールマイカ	カラーNo. ()	エアコン QW・AAG・WAG・()	装備品のみにO印を記入	
内装色 ()	内装 ()	乗車定員 6人	サンルーフ 革シート	
左・右 左・右	輸入 区分	ディーラー ・ 銀行	リサイクル料 13,480円	販売税 エコノミック
セールスポイント				
純正ナビ/リアゲルダカメラ 社外 10.2インチ/アイアクティブセンス (マツダ) /シートヒーター/車線逸脱防止支援システム/ヘッドランプ LED/Bluetooth接続				
検査記入欄				
外装備				
A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ Q ガラスキズ W 補修跡 S ヤビ C 腐食 X 交換部 YX 交換部				
登録No. 月 日 までに名実である方				
車体番号 KG5P-100846				
シリアル No.				
FW トンネル	ワレ	外装 小	ホイール	エアロ
内装	シシ	ヤブレ	コガ	コガ穴
オーディー穴				
取組				
長さ cm 幅 cm 高さ cm 最大積重量 Kg				