

2018 MAZDA CX-8 XD		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-KG2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/06	MILEAGE 88,000 km		
DOORS 5	DRIVETRAIN 2WD (FF)		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Gray		
BODY TYPE SUV			
CHASSIS NO. KG2P-117677	DIMENSIONS (L X W X H) 490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels Cruise Control Back Camera Navigation System		Pre-Collision Braking Side Camera Adaptive Cruise Control	
INSPECTOR REPORT			
Interior dirt, seat edge scuffs, steering wheel scuffs, trunk trim scratches, small scratches and dents			

ORIGINAL JAPANESE AUCTION SHEET

年式 H30 6月	メーカー マツダ	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 C X - 8	グレード X D	駆動方式 4WD	燃費区分 4WD	
車種 自家用 ・ その他 ()	排気量 2200	形式 3DA-KG2P	国産 輸入車	内装 A・⑨・C
登録 - - 年 / 月 / 日	ガソリン ハイブリッド ()	シフト AT	後付選用品 (保証書 ・ 取扱説明書 等)	
走行 88,000	マイル 000	AT		
外装色 グレー	カラーNo. ()	エディション AG・⑨・WAG・()	装備品のみ・C印を記入	
内装色 ()	乗車定員 人	人	サンルーフ	革シート
走行 左・()	輸入 ディーラー・直行	12,860円	エアバック	キーレス
セールスポイント				
純正ナビゲーション TVチューナー (CD/DVDプレイヤー付) セーフティクルーズパッケージ スマートキー*2				
検査記入欄				
ルーム内汚れ シートフチスレ ハンドルスレ 荷室トリムキズ 小キズ小凹				
修復歴 有・⑥				
A キズ B ハコボネサレ C キズ・ハコボネ D 色あせ・サビ E ガラスキズ W 腐食 F サビ G 腐食 H 交換車 I 交換車 J 交換車 K 交換車 L 交換車 M 交換車 N 交換車 O 交換車 P 交換車 Q 交換車 R 交換車 S 交換車 T 交換車 U 交換車 V 交換車 W 交換車 X 交換車 Y 交換車 Z 交換車				
名義中 月 日 までに名義で受取る方				
車検 番号 KG2P-117677				
長さ cm 幅 cm 高さ cm 最大積重量 kg				