

2018 MAZDA CX-8 XD L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-KG2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/01	MILEAGE 65,000 km		
DOORS 5	SEATS 6		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Other		
BODY TYPE SUV			
CHASSIS NO. KG2P-101330	DIMENSIONS (L X W X H) 490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels Leather Seats (Nappa Leather) Power Seats (Front) Adaptive Cruise Control Back Camera Navigation System		Roof Rails Power Tailgate Pre-Collision Braking Side Camera 360° Camera	
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been repaired, but minor scratches and dents remain. Interior: Some noticeable dirt and stains are present in parts. Accident History: No abnormalities in the frame.			

[illegible]