

2018 MAZDA CX-8 XD L Package		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE KG2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/12	MILEAGE 58,370 km		
DOORS 5	DRIVETRAIN 4WD		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Black		
BODY TYPE SUV			
CHASSIS NO. KG2F-201159	DIMENSIONS (L X W X H) 490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Leather Seats (Nappa Leather) Adaptive Cruise Control Back Camera		Roof Rails Power Seats (Front) Pre-Collision Braking Side Camera	
INSPECTOR REPORT			
Glass: Good, but some areas need repair and have scratches. Seats: Good, but with burn marks, holes, stains, tears, wear, and sagging. Handbrake lever noted. Headliner: Scratches and pilling. Idle stop system: Poor function, needs check, intermittent. Navigation/Steering: Scratches, condition issues, and cracks. Headlights: Fading, rust, and scratches. Undercarriage: Front and rear impact damage, rust. Core support, right front inner panel, left front side member, right pillar, left pillar, and end panel are bent. Right pillar also has panel damage. Lower support and rear floor noted.			

ORIGINAL JAPANESE AUCTION SHEET

[illegible]