

2018 Mazda CX-8 XD L Package

OVERALL

3.5

EXTERIOR

INTERIOR

-

-

MODEL CODE

KG2P

DISPLACEMENT

2,188 cc

YEAR / REG.

2018/02

MILEAGE

93,532 km

DOORS

5

SEATS

6

TRANSMISSION

AT

FUEL

Diesel

STEERING

Right

EXTERIOR COLOR

Red

BODY TYPE

SUV

CHASSIS NO.

KG2P-105645

DIMENSIONS (L X W X H)

490 × 184 × 173 cm

SALES POINTS

Alloy Wheels

Leather Seats (Nappa Leather)

Power Seats (Front)

Adaptive Cruise Control

Back Camera

Navigation System

Roof Rails

Power Tailgate

Pre-Collision Braking

Side Camera

360° Camera

INSPECTOR REPORT

F pillar small dent, exterior line scratches

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H30/2月	メーカー マツダ	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 3.5
車名 CX-8	グレード XD	駆動方式 2WD	4WD	
車種 乗用車・その他 ()	排気量 2200 cc	型式 KG2P	登録区分 A・⑤・C	
走行 93,532 km	燃料 ガソリン	変速機 AT	後付部品 (保証書・取扱説明書等)	
外装色 ソウルレッドタリスタルメタリック	カラーNo. 46V	エアコン ④・AAG・WAG・ ()	装備品のみのO印を記入	
内装色 ()	乗車定員 6人	⑤	⑥	⑦
⑧	⑨	⑩	⑪	⑫
⑬	⑭	⑮	⑯	⑰
⑱	⑲	⑳	㉑	㉒
㉓	㉔	㉕	㉖	㉗
㉘	㉙	㉚	㉛	㉜
㉝	㉞	㉟	㊱	㊲
㊳	㊴	㊵	㊶	㊷
㊸	㊹	㊺	㊻	㊼
㊽	㊾	㊿		
セールスポイント BOSEサウンド 純正ナビ フルセグBluetooth 全方位カメラ 衝突軽減ブレーキレーンアシスト クリアランスソナー ヘッドアップディスプレイ ブラインドスポットモニター パワーバックドア	修復歴 有・⑥			
検査記入欄 Fビラー小U 外装線傷	A 欠損 U ヘッドランプ B キズ・ヘコみ P 色あせ・汚れ G ガラスキズ W 腐食 S サビ C 変色 X 交換 ㉑ 交換 登録年月日 月 日 までにご来店ください 車体番号 KG2P-105645			
内装 ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	長さ cm 幅 cm 高さ cm 最大積載量 kg			