

2018 MAZDA CX-8 XD PROACTIVE		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-KG2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2018/09	MILEAGE 81,000 km		
DOORS 5	SEATS 7		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Other		
BODY TYPE SUV			
CHASSIS NO. KG2P-125780	DIMENSIONS (L X W X H) 490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Cruise Control 360° Camera	
INSPECTOR REPORT			
Exterior: Major scratches and dents have been repaired, but minor scratches and dents remain. Interior: There are some noticeable stains, but only in parts. Repair history: No abnormalities in the frame components.			

軽年次車検 H30		車名 マツダ		ドア数 5		ボディ形状 SUV/クロカン		評価点 4	
9月		C X-8		グレード XD PROACTIVE					
自家用		右		3DA-KG2P		定容量 2200		燃料 ディーゼル	
9年 9月 / 経過		走行 81,000		マル 0.0		燃費 AC		安全装備 K	
外装 マツダ「グレート・プレミアム」		カラー-No.		リサイクル料		価格 12,860円		保証書番 KG2P-125780	
()		内装 シフト フロア AT		車庫 7		長さ cm		高さ cm	
(保証書・取扱説明書等)									

車検前点検項目: 点検項目がすべて正常で合格判定となります。点検項目が正常でない項目は、点検項目の欄に「点検項目が正常でない」と記載されます。点検項目が正常でない項目は、点検項目の欄に「点検項目が正常でない」と記載されます。

車検前点検項目					
車検前 2020年6月10日	車検前 2020年6月10日	車検前 2020年6月10日	車検前 2020年6月10日	車検前 2020年6月10日	車検前 2020年6月10日
マツダ「グレート・プレミアム」	マツダ「グレート・プレミアム」	マツダ「グレート・プレミアム」	マツダ「グレート・プレミアム」	マツダ「グレート・プレミアム」	マツダ「グレート・プレミアム」

マツダ「グレート・プレミアム」に関する注意事項

車検前点検項目: 点検項目がすべて正常で合格判定となります。点検項目が正常でない項目は、点検項目の欄に「点検項目が正常でない」と記載されます。点検項目が正常でない項目は、点検項目の欄に「点検項目が正常でない」と記載されます。