

2018 Mazda CX-8 XD Proactive		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-KG2P	2,188 cc		
YEAR / REG.	MILEAGE		
2018/12	87,323 km		
DOORS	TRANSMISSION		
5	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Station Wagon		
CHASSIS NO.	DIMENSIONS (L X W X H)		
201963	490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Side Camera	
Back Camera		360° Camera	
Navigation System			
INSPECTOR REPORT			
Seat stains, interior scratches, door mirror scratches			

ORIGINAL JAPANESE AUCTION SHEET

印年度登録 H30 12月	メーカー マツダ 車名 CX-8	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 4.5
車種 自家用・その他 ()	排気量 2200 CC	型式 3DA-KG2P	登録 形式	内装 A・⑨・C
車検 - - 年 月 / 日	燃料 ガソリン ハイブリッド ()	シフト フロア	AT	後日送り品 (保証書・取扱説明書 等)
走行 87,323 km	外装色 シルバー	カラーNo. 45P	エアコン AG・⑧・WAG・ ()	装備品のみ O印 を記入
左・右 左・右	内装色 ()	登録年月 2018年12月	13,480円	⑨ ⑧ ⑦ ⑥ ⑤ ④ ③ ② ①
セールスポイント 360° カメラ		修復歴 有・⑨		
検査記入欄 シートヨゴレ、内装キズ、ドアミラーキズ		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 傷跡 S ヤビ C 腐食 X 交換部 Y 交換部 Z 交換部		
登録No. 201963		名義中 月 日 までに名義できる方		
内装 ⑨ ⑧ ⑦ ⑥ ⑤ ④ ③ ② ①		車検 201963		
シリアル No.		車検 201963		
内装 ⑨ ⑧ ⑦ ⑥ ⑤ ④ ③ ② ①		車検 201963		