

2018 MAZDA Demio 1.3 13S Touring		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-DJ3FS	DISPLACEMENT 1,298 cc		
YEAR / REG. 2018/04	MILEAGE 28,011 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Hatchback		
CHASSIS NO. DJ3FS-517727	DIMENSIONS (L X W X H) 406 × 169 × 152 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Front glass: Scratches, stone chips, cracks, repair marks, replacement needed. Interior: Scratches, dirt, burns, holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成30年 4月	車名・グレード デミオ 13Sツーリング	2WD 4WD	評価点 (4.5)
ディーラー・並行 モデル年式 年	型式 DBA-DJ3FS	排気量 1300 CC	ドア 5 形状 木
ハンドル 左・右		定員 5人	積載 kg
			外装 内装 B B
車歴 自家用	シフト FAT	セールスポイント (正常に機能するものに限りです)	
車検 令和9年 4月 (日)	冷却 AAC	スマートキー・☆ETC・☆HIDヘッドライト	
走行 2万8千011 km	燃料 ガソリン	衝突軽減ブレーキ BSM HID	
色 レッド	色替 色コード 46V	装備品 (純正品に限り○をつけてください)	
R券 10,040 円		(PS) (PW) (BS) (TB) (AW) SR ナビ TV カワ	
注意事項申告欄		新車保証書 未日品 有・無	
外装 小A・小U			
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ	A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
車台番号 517727		型式指定番号 17795	個別区分番号 0262
登録番号 袖ヶ浦 501 ね 9437		車体寸法 長さ 406 幅 169 高さ 152	