

2018 MAZDA Demio 1.5 15S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6BA-DJLFS	DISPLACEMENT 1,496 cc		
YEAR / REG. 2018/09	MILEAGE 86,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. DJLFS-602158	DIMENSIONS (L X W X H) 406 × 170 × 153 cm		
SALES POINTS			
Alloy Wheels Navigation System		360° Camera	
INSPECTOR REPORT			
PW: Stone chip. Interior: Dirt, stains, tears, burns, burn holes, scuffs. Exterior: Minor damage, cracks. Wheels: Scratches, bends, cracks. Aero parts: Cracks.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H30 9月	メーカー マツダ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 デミオ	グレード 1.5 15S 衝突被害軽減ブレーキ 純正ナビ	駆動方式 2WD	4WD	
車種 自家用・その他	排気量 1500 cc	型式 6BA-DJLFS	燃費 A・B・C	
年 -	月 -	日 -	燃料 ガソリン	ディーゼル
走行 86,000 km	フロア 6 MT	乗車人数 5人	新車のみ O印 を記入	
外装色 スノーフレックホワイトパールマイカ	カラーNo. Qd・AAG・WAG・()	エアコン	AW	サンルーフ
小 左・右	大 左・右	10,040円	エアロック	スベア
セールスポイント				
キーレスエントリー/ABS/運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/メモリーナビ他/フルセグTV/衝突被害軽減ブレーキ/アイドリングストップ/スマートキー/盗難防止システム/LEDヘッドライト/横滑り防止装置(ESC)/シートヒーター/DVD再生/CD/全周距カメラ/フロントカメラ/サイドカメラ/バックカメラ/障害物センサー				
検査記入欄				
A キズ U ヘッドサレ B キズヘコ P 色あせ・汚れ Q ガラスズレ W 腐蝕 S サビ C 腐食 X 交換品 XX 交換済 車検No. 月 日 までには車検できる方 車検番号 DJLFS-602158				
FW	シリアル No.	長さ cm	幅 cm	高さ cm
内装 3ゴレ	シロ	ヤブレ	コガ	コガス