


2018 Mazda Demio 13S Touring		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-DJ3FS	DISPLACEMENT 1,298 cc		
YEAR / REG. 2018/01	MILEAGE 16,576 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Hatchback		
CHASSIS NO. DJ3FS-502956	DIMENSIONS (L X W X H) 406 × 170 × 150 cm		
SALES POINTS			
Alloy Wheels Navigation System		Pre-Collision Braking	
INSPECTOR REPORT			
Minor scratches/dents on driver's side mirror, trim, and cargo area. Seat wear.			

ORIGINAL JAPANESE AUCTION SHEET

H30/1月		マツダ デミオ		5	コンパクトハッチバック		4																				
車種 自家用・その他()		排気量 1290	型式 DBA-DJ3FS	燃料 ガソリン	駆動方式 2WD	内装 A・B・C																					
年 16		月 5		日 7		走行 16,576																					
車検 16/5/7		AT		ナビSD、スベアキー																							
外装色 レッド		カラーNo. ()		装備品のみ O印 を記入																							
内装色 ()		乗車定員 5人		サンルーフ 革シート																							
左・前 ディーラー		走行 10,040円		エブリック																							
セールポイント オートライト、プッシュスタート、MRCC、ステアリングスイッチ、Fシートヒーター、t-stop、バックカメラ、ESC、IS、AEB																											
検査記入欄 DミラーA、トリムA、シートスレ、荷室内A				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘビイサレ</td><td>B</td><td>キズヘビ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>腐蝕跡</td><td>S</td><td>サビ</td><td>C</td><td>変色</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘビイサレ	B	キズヘビ	P	色あせ・ボケ	G	ガラスキズ	W	腐蝕跡	S	サビ	C	変色	X	交換済	XX	交換済
A	キズ	U	ヘビイサレ	B	キズヘビ	P	色あせ・ボケ	G	ガラスキズ																		
W	腐蝕跡	S	サビ	C	変色	X	交換済	XX	交換済																		
登録No. DJ3FS-502956				名義中 月 日 まで																							
FW 内装				シリアルNo. 車種																							