

2018 Mazda FLAIR WAGON Hybrid XS		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE MM53S	DISPLACEMENT 658 cc		
YEAR / REG. 2018/08	MILEAGE 61,000 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Hybrid (Petrol)		
STEERING Right	EXTERIOR COLOR Blue		
BODY TYPE Kei			
CHASSIS NO. MM53S-102065	DIMENSIONS (L X W X H) 340 × 148 × 179 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Power Sliding Doors (Both Sides) (Both...		Pre-Collision Braking	
Navigation System			
INSPECTOR REPORT			
Interior has scratches and dirt. Seats have scuffs and wrinkles. Exterior has minor and light scratches. Acquired with an AA rating of 4.5 points.			

ORIGINAL JAPANESE AUCTION SHEET

型式番号 H30/8月	メーカー マツダ	ドア数 5	ボディタイプ 軽四	評価点 4.5
車名 フレアワゴン	グレード ハイブリッドXS	駆動方式 2WD 4WD		
車種 自家用・その他()	排気量 660 cc	型式 MM53S	通称 軽四	内装 A・B・C
年 月	燃料 ガソリン	ディーゼル	登録区分 2WD 4WD	
走行 61,000 km	インパネ	AT	登録区分 2WD 4WD	
外装色 オフブルメタリックII	カラーNo.	エンジン	登録区分 2WD 4WD	
内装色 ()	4人	登録区分 2WD 4WD	登録区分 2WD 4WD	
走行 9,770 km	登録区分 2WD 4WD	登録区分 2WD 4WD	登録区分 2WD 4WD	
セールスポイント CD/バックカメラ/横滑り防止装置(ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビ/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/ベンチシート/DVD再生/両側電動スライドドア				
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装キズ、薄キズ AA評価4.5点仕入れ				
修復歴 有・無				
A キズ B へこみ C 凹み D 色あせ E 汚れ F 交換部 G 交換部 H 交換部 I 交換部 J 交換部 K 交換部 L 交換部 M 交換部 N 交換部 O 交換部 P 交換部 Q 交換部 R 交換部 S 交換部 T 交換部 U 交換部 V 交換部 W 交換部 X 交換部 Y 交換部 Z 交換部				
車検 MM53S-102065				
車検 MM53S-102065				
車検 MM53S-102065				
車検 MM53S-102065				