

| 2018 Mercedes-Benz CLS Class<br>CLS220d Sport Exclusive Package                                                                                                                                                                                                                   |                                              | OVERALL                                                                                                                                            |          |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|----------|
|                                                                                                                                                                                                                                                                                   |                                              | EXTERIOR                                                                                                                                           | INTERIOR |
|                                                                                                                                                                                                                                                                                   |                                              | 4.5                                                                                                                                                |          |
|                                                                                                                                                                                                                                                                                   |                                              | -                                                                                                                                                  | -        |
| MODEL CODE<br>LDA-257314                                                                                                                                                                                                                                                          | DISPLACEMENT<br>1,949 cc                     |                                                                                                                                                    |          |
| YEAR / REG.<br>2018/11                                                                                                                                                                                                                                                            | MILEAGE<br>57,000 km                         |                                                                                                                                                    |          |
| DOORS<br>4                                                                                                                                                                                                                                                                        | SEATS<br>5                                   |                                                                                                                                                    |          |
| DRIVETRAIN<br>2WD (FR)                                                                                                                                                                                                                                                            | TRANSMISSION<br>AT                           |                                                                                                                                                    |          |
| FUEL<br>Diesel                                                                                                                                                                                                                                                                    | STEERING<br>Right                            |                                                                                                                                                    |          |
| EXTERIOR COLOR<br>White                                                                                                                                                                                                                                                           | BODY TYPE<br>Sedan                           |                                                                                                                                                    |          |
| CHASSIS NO.<br>WDD2573142A024342                                                                                                                                                                                                                                                  | DIMENSIONS (L X W X H)<br>500 × 189 × 142 cm |                                                                                                                                                    |          |
| SALES POINTS                                                                                                                                                                                                                                                                      |                                              |                                                                                                                                                    |          |
| Sunroof<br>Power Seats (Front)<br>Pre-Collision Braking<br>Parking Assist (Auto Steering)<br>Side Camera<br>Navigation System                                                                                                                                                     |                                              | Alloy Wheels<br>Leather Seats (Nappa Leather)<br>Adaptive Cruise Control<br>Front Camera<br>Back Camera<br>Burmester Surround Sound System (13 ... |          |
| INSPECTOR REPORT                                                                                                                                                                                                                                                                  |                                              |                                                                                                                                                    |          |
| Stone chips on front glass, bonnet, and front bumper. Minor scuff on the lower right front bumper. Small scratches on the right front door's aluminum molding and the rear bumper's left center pillar. Curb rash on the left front wheel. Seat wrinkles and steering wheel wear. |                                              |                                                                                                                                                    |          |

[illegible]