

2018 MINI Clubman Cooper Clubman		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LN15	DISPLACEMENT 1,498 cc		
YEAR / REG. 2018/03	MILEAGE 11,420 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Purple	BODY TYPE Hatchback		
CHASSIS NO. WMWLN320202F17107	DIMENSIONS (L X W X H) 427 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Sunroof Back Camera	
INSPECTOR REPORT			
Minor A-grade damage on pillar lining, luggage compartment lining, and console. BO repair marks.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/3月	メーカー MINI	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価値 4.5
車名 MINI	グレード クーパー クラブマン	駆動方式 4WD	4WD	
車種 自家用・その他 ()	排気量 1500 cc	型式 DBA-LN15	通称 ミニ	内装 A・B・C
年 9	月 3	年 3	燃料 ハイブリッド	ディーゼル
走行 11,420 km	走行 11,420 km	走行 11,420 km	フロア	AT
外装色 パープル	カラーNo. ()	QD・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5 人	サンルーフ	車シート	
左・前・後 左・前・後	走行 19,440 km	エンジン	エアコン	ABS
セールスポイント				
ワンオーナー/純正ナビ、バックカメラ、フルセグTV/障害物センサー/ACC/ETC/HID/純正17AW/アイドリングストップ				
修復歴 有・無				
検査記入欄				
AIS 査定評価				
ビラー内張りA(小) 荷室内張りA(小)				
コンソールA(小) BO修理跡				
車体番号 WMWLN320202F17107				
信号 No.				
内装 トビ石 傷A フレ 外装 小 A・U ホイル A・曲 A・フレ エアロ				
内装 ヨゴレ シミ ヤブレ コガ コガ穴 オーディオ穴 スレ				
車高 0 cm 0 cm 0 cm 最大全高 0 cm				