

2018 MITSUBISHI Delica D5 4WD_D Power Package		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE LDA-CV1W	DISPLACEMENT 2,267 cc		
YEAR / REG. 2018/10	MILEAGE 61,900 km		
DOORS 5	SEATS 8		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Minivan		
CHASSIS NO. CV1W-1305141	DIMENSIONS (L X W X H) 479 × 180 × 187 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Power Sliding Doors (Both Sides) (Both... Back Camera	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/10月	メーカー 三菱	ドア枚数 5	ボディ形状 ミニバン/ワンボックス	評価点 4
車名 デリカD : 5	グレード 4WD_D/パワーパッケージ	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 2200 CC	型式 LDA-CV1W	選装 型式	内装 A・B・C
車検 9年10月	抹消 燃料 ガソリン ハイブリッド ()	シフト AT	後付選用品 (保証書・取扱説明書 等)	
走行 61,900 km	カラーNo. ウォームホワイトパールスターリングSM	エアコン QW・AAG・WAG・ ()	装備品のみ O印 を記入	
外装色 ()	内装色 ()	乗車定員 8人	サンルーフ 革シート	
左・右 左・右	輸入 区分	ディーラー 並行	14,710円	販売額 エコマーク
セールスポイント				
社外ナビ/衝突安全装置/両側電動スライドドア/シートヒーター 前席/ヘッドランプ LED/Bluetooth接続/ETC/EBD付ABS/横滑り防止装置/フルセグTV/DVD				
検査記入欄				
外装AU				
修理歴 有・無				
A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ Q ガラスキズ W 擦傷跡 S ヤビ C 腐食 X 交換部 YX 交換部				
登録No. 月 日 までに名義である方				
車体番号 CV1W-1305141				
シリアル No.				
全長 全幅 高さ 最大積載量 Kg				