

2018 MITSUBISHI ek Space G Safety Package		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-B11A	DISPLACEMENT 659 cc		
YEAR / REG. 2018/05	MILEAGE 32,029 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Station Wagon		
CHASSIS NO. B11A-0306601	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Drive... Front Camera Back Camera Navigation System		Pre-Collision Braking Side Camera 360° Camera	
INSPECTOR REPORT			
Interior cigarette smell, yellowed headliner, seat stains, trim dirt, right front liner bent/damaged, right lower support distorted, front bumper misaligned.			

初年度登録	三菱	5	ステーションワゴン	評価点																		
H30/5月	車名 eKスペース	グレード Gセーフィッパ ケージ	車検区分 緑0 4WD	9.5																		
車種 自家用・その他	排気量 660	型式 CC	DBA-B11A	内装 A・B・C																		
車検 - 年 月 日	納期 先着 ハイブリッド	ディーゼル	後付選り品（保証書・取扱説明書等）																			
走行 0回にオーバーホール（点検）・交換（点検）	シフト インパネ	AT																				
外装色 シルバー（A31）	エンジン AD・WD・WAD・（）	新車品のみ O印 を記入																				
（ ）	内装色 （ ）	乗車人数 4人																				
左・右 左・右	カラー ディーゼル・走行	サイズ 9,190円	オプション E	オプション F																		
セールスポイント																						
検査記入欄																						
車内タバコ臭、天張り黄ばみ シート染み、トリム汚れ 右フライヤー曲がり・破損 右ロアサポート歪み Fバンパーずれ		修復歴 有。⑥ <table border="1"> <tr> <td>A</td> <td>ボディ</td> <td>U</td> <td>フロントササ</td> <td>B</td> <td>ボディ後部</td> <td>色あせ・汚れ</td> <td>G</td> <td>ガラス・窓</td> </tr> <tr> <td>W</td> <td>補修跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>衝突</td> <td>X</td> <td>交換歴</td> <td>XX</td> </tr> </table> 登録地 月 日 家で二名乗で走る 車体番号 B11A-0306601 シリアル No.			A	ボディ	U	フロントササ	B	ボディ後部	色あせ・汚れ	G	ガラス・窓	W	補修跡	S	サビ	C	衝突	X	交換歴	XX
A	ボディ	U	フロントササ	B	ボディ後部	色あせ・汚れ	G	ガラス・窓														
W	補修跡	S	サビ	C	衝突	X	交換歴	XX														
PW Hド右 備A フレ 内装 小 オイル エアロ ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ A・ワレ		内装 ⑩ ⑪ ヤレ ⑫ コガ ⑬ コガ ⑭ オークス ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿																				