

2018 Nissan Dayz RooxHighWayStar Highway Star X		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE B21A	DISPLACEMENT 659 cc		
YEAR / REG. 2018/01	MILEAGE 42,000 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Brown		
BODY TYPE Kei			
CHASSIS NO. B21A-0383334	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Side Camera 360° Camera		Power Sliding Doors (Both Sides) (Drive... Front Camera Back Camera Navigation System	
INSPECTOR REPORT			
Interior has scratches and dirt. Seats show scuffs and wrinkles. Exterior has minor and light scratches. Rear panel is distorted. AA rating is 3.5.			

ORIGINAL JAPANESE AUCTION SHEET

H30 1月	メーカー 日産	ドア数 5	ボディ形状 軽四	評価点 3.5
車名 1月 デイズルークス	グレード ハイウェイスター X	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 660 cc	型式 B21A	内装 A・⑤・C	
年 9	月 1	日 1	燃料 ガソリン	ディーゼル
走行 42,000 km	メーター 000	インパネ	AT	
外装色 モカブラウンP	カラーNo. ()	エアコン ④・AAG・WAG・()	装備品のみ・O印を記入	
内装色 ()	乗車定員 4人	⑤	サンルーフ	革シート
左・()	右・()	8,230円	⑤	⑥
セールスポイント				
バックカメラ/ETC/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディアイドリングストップ/ベンチシート/全周カメラ/フロントカメラ/サイドカメラ				
修復歴 有・⑥				
検査記入欄				
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価3.5点仕入れ Rパネル雪み				
A キズ B ハコボケサレ C キズ・ヘコみ D 色あせ・サビ E ガラスキズ W 腐食 F サビ G 腐食 H X 交換機 Y 交換機				
名義中 月 日 まで B21A-0383334				
FR ⑤	MR ⑤	FR ⑤	MR ⑤	FR ⑤
FR ⑤	MR ⑤	FR ⑤	MR ⑤	FR ⑤