


2018 Nissan Leaf G		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ZAA-ZE1	1 CC		
YEAR / REG.	MILEAGE		
2018/02	68,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Electric	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ZE1-009662	448 × 179 × 154 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Pre-Collision Braking		Adaptive Cruise Control	
Cruise Control		Parking Assist (Auto Steering)	
Front Camera		Side Camera	
Back Camera		360° Camera	
Navigation System			
INSPECTOR REPORT			
Exterior: Minor scratches and dents. Seats: Sagging. Interior trim: Scratches. Front glass: Scratches, stone chips, cracks, repair marks, needs replacement. Interior: Scratches, stains, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成30年 2月	車名・グレード リーフ G	(2WD) 4WD	評 価 点 (4)		
ディーラー・並行 モデル年式 ハンドル 左・右	型式 ZAA-ZE1	排気量 EV CC 形状 HB 定員 5人 積載 kg	外 装 B 内 装 B		
車種 自家用	シフト CVT	セールスポイント (正常に機能するものに限りです)			
車検 令和9年 2月 (日)	冷房 AAC	メーカーナビ・アラウンドビュー			
走行 6万7千300 km	燃料 電気	BOSEサウンド・インテリジェントルームミラー			
色 パール2	色コード XBK	プロパイロット・フルセグTV			
R券 9,550 円		装備品 (純正品に限り○をつけてください)			
注意事項申告欄		(PS) (PW) (ABS) (エアB) (AW) (SR) (ナビ) (TV) (カメラ)			
外装 小A・小U シート へたり 内張り キズ		新車保証書 後日品 有・無			
フロントガラス キズ・破れ・ヒビ割・リペア跡・X要 内装 (キズ)・汚レ・コゲ・穴・スレ・キレ・破レ					
車台番号 009662	A-キズ E-エクゴ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済				
登録番号 名変中	型式指定番号 登録区分番号 車検有効期 備考				