

2018 Nissan X-TRAIL 20Xi		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
NT32	1,997 cc		
YEAR / REG.	MILEAGE		
2018/09	67,657 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
NT32-096448	469 × 182 × 174 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Power Tailgate		Pre-Collision Braking	
Adaptive Cruise Control		Front Camera	
Side Camera		Back Camera	
360° Camera		Navigation System	
INSPECTOR REPORT			
Exterior: Minor scratches and dents have been repaired, but some small ones remain. Interior: Some noticeable dirt is present in parts. Repair history: No abnormalities in the frame.			

年号登録番号 H30 日産 5 SUV/クロカン 評価点	
車内灯の付く一級品/JAA安全認定の評価と下部記載の評価値は異なります	
車種 H30 エクストレイル 20Xi	
年式 9月 NT32 2000 ガソリン	
車体色 白 右 左	
年式 9年 9月 抹消	
年式 9年 9月 抹消	
プリオリートホワイトパール カラー-No. リサイクル料	
10,120円 販売店	
車体番号 NT32-096448	
() 登録料(1万円) 消費税(1万円)	
シフト フロア AT	
乗車人数 5人	
車体色 白	
車体色 白	
車体色 白	

車体点検結果

車体点検結果は、車体点検員が点検した結果に基づき、以下のとおり記載しております。点検結果は、点検員が点検した結果に基づき、以下のとおり記載しております。点検結果は、点検員が点検した結果に基づき、以下のとおり記載しております。

車体点検結果は、車体点検員が点検した結果に基づき、以下のとおり記載しております。点検結果は、点検員が点検した結果に基づき、以下のとおり記載しております。点検結果は、点検員が点検した結果に基づき、以下のとおり記載しております。

車体点検結果

車体点検結果は、車体点検員が点検した結果に基づき、以下のとおり記載しております。点検結果は、点検員が点検した結果に基づき、以下のとおり記載しております。点検結果は、点検員が点検した結果に基づき、以下のとおり記載しております。

車体点検結果は、車体点検員が点検した結果に基づき、以下のとおり記載しております。点検結果は、点検員が点検した結果に基づき、以下のとおり記載しております。点検結果は、点検員が点検した結果に基づき、以下のとおり記載しております。