

2018 Porsche Cayenne Turbo

OVERALL

4

EXTERIOR

-

INTERIOR

-

MODEL CODE

E3K40A

DISPLACEMENT

3,996 cc

YEAR / REG.

2018/07

MILEAGE

50,000 km

DOORS

5

SEATS

5

DRIVETRAIN

4WD

TRANSMISSION

AT

FUEL

Petrol

STEERING

Right

EXTERIOR COLOR

Black

BODY TYPE

SUV

CHASSIS NO.

WP1ZZZ9YZKDA90889

DIMENSIONS (L X W X H)

493 × 199 × 168 cm

SALES POINTS

Alloy Wheels

Roof Rails

Power Tailgate

Adaptive Cruise Control

Side Camera

Navigation System

Sunroof

Leather Seats (Leather)

Power Seats (Front)

Front Camera


Back Camera

Bose (710W14SP)

INSPECTOR REPORT

Dashboard lifting

ORIGINAL JAPANESE AUCTION SHEET

H30 / 7月		ポルシェ カイエン ターボ		5	SUV/クロカン	4																				
車種	白車用・その他 ()	排気量	4000 cc	型式	E3K40A	内装																				
車検	9年12月 / 扶養	燃料	ガソリン	ディーゼル	ハイブリッド ()	後日選用品 (保証書・取扱説明書等)																				
走行	50,000 km	変速機	AT																							
外装色	ブラック	カラーNo.		エアコン	AG・AC・WAG ()	新選用品のみ O印 を記入																				
内装色	()	車検年度		人																						
左・前・後・右	左・前・後・右	走行	31,090円	エンジン	ナビ	TV																				
セールスポイント																										
純正ステアリング有・純正モニター有				修復歴 有・O																						
検査記入欄				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・サビ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>腐食跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>			A	キズ	U	ヘコみ・サビ	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ	W	腐食跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ・サビ	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ																	
W	腐食跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
ダッシュ浮き				名義中																						
				月 日 までにご来店ください																						
				車検番号 WP1ZZZ9YZKDA90889																						
内装	3ボレ	シス	ヤブレ	コダ	コダス	オーディウス																				
内装	3ボレ	シス	ヤブレ	コダ	コダス	オーディウス																				