

2018 Renault Twingo GT		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ABA-AHH4B1	897 cc		
YEAR / REG.	MILEAGE		
2018/04	49,300 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (RR)	MT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Orange	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
VF1AHB525H0770017	363 × 166 × 155 cm		
SALES POINTS			
Alloy Wheels		Cruise Control	
INSPECTOR REPORT			
Exterior: Major scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains are present. Frame: No abnormalities.			

H30 4月		新年度登録 メーカー ルノー		ドア枚数 5		ボディ形状 コンパクトハッチバック		評価点 4.5																	
		車名 トゥインゴ		グレード GT																					
車種 自家用		販売店 ディーラー		型式 ABA-AHH4B1		排気量 900		燃料 ガソリン																	
車体色 オレンジ		走行距離 12,470 km		乗車定員 4人		駆動方式 2WD		安全装置 AC																	
年式 9年6月		カラーNo. ()		リサイクル料 0円		車両番号 VF1AHB52H0770017		内装色 B																	
()		シフト フロア 5 MT		長さ cm		幅 cm		高 cm																	
後日送り状 (保証書・取扱説明書等)																									
装備 ◎AV ◎V ◎W ナビ TV ◎S																									
セールスポイント																									
車庫状態の検閲 検査日 2020年6月15日 再検査日 _____ クオリティグレード 外装 ★★★★★ 内装 ★★★★★ 駆動装置 投接点 燃費 正所																									
車両状態の検閲 <table border="1" style="width: 100%;"> <thead> <tr> <th>小</th> <th>A4サイズ未満</th> <th>中</th> <th>A4サイズ以上</th> <th>大</th> <th>A4サイズ以上</th> <th>数量</th> <th>金額(円)</th> </tr> </thead> <tbody> <tr> <td>見知品</td> <td>交換品</td> <td>修理品</td> <td>廃止品</td> <td>その他</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>										小	A4サイズ未満	中	A4サイズ以上	大	A4サイズ以上	数量	金額(円)	見知品	交換品	修理品	廃止品	その他			
小	A4サイズ未満	中	A4サイズ以上	大	A4サイズ以上	数量	金額(円)																		
見知品	交換品	修理品	廃止品	その他																					
※本表は商品の状態を確認する際に使用いたします。(取り違えありません) [例] 見知品→一輪おとりセンター取付車(変更済み) 見知品 タイヤに交換 修理品 交換品 タイヤに交換 見知品 タイヤに交換 タイヤ 見知品 タイヤに交換 交換品 タイヤに交換 見知品 タイヤに交換 交換品 タイヤに交換 <注> 見知品とは、交換品と異なり、修理品と見做すものとします。																									
※ダメージレベルに関する注意事項 傷に記号のふ 小傷？ 必ず 小 ⇒ A 中傷？ 必ず 中 ⇒ B 大傷？ 必ず 大 ⇒ C 必ず へ に 必 死 ⇒ ALD																									
クオリティグレード説明 外装：無になる平ズやヘコミは補修済みですが、小さな平ズやヘコミが残っています。 内装：無になる汚れ等が、部分的にあります。 修理歴：骨格部位に異常はありません。																									