

2018 SUBARU SUBARU OTHER 2.0i-S EyeSight 4WD Hail Damage 8-inch Navi		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-GT7	DISPLACEMENT 1,995 cc		
YEAR / REG. 2018/09	MILEAGE 68,820 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Station Wagon		
CHASSIS NO. GT7-077782	DIMENSIONS (L X W X H) 446 × 180 × 159 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Numerous dents on top surface. Rear (roof) spoiler partially faded and paint peeling. Partial stone chips. Other trim parts with wrinkles, scuffs, and scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式車種 H30/9月	メーカー スバル	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 3.5
車名 スバルその他	グレード 2.0 I-S アイサイト 4WD 雲間み 8インチ	駆動方式 2WD	燃費区分 40.0	
車庫 自家用・その他()	排気量 2000 cc	型式 DBA-GT7	選定 型式	内装 A・⑨・C
車検 9年9月/抹消	燃料 ガソリン	ディーゼル	後日選り品(保証書・取扱説明書等)	
走行 68,820マイル	フロア	CVT		
外装色 グレー	カラーNo. ()	エアコン ④⑥・AAG・WAG・()	新着品のみ O印 を記入	
小 左・⑧	輸入 区分	ディーラー 車行	11,870円	販売税
セールスポイント		車体番号 GT7-077782		
検査記入欄		修復歴 有・⑨		
上面凹み多数 リヤ(ルーフ)スポイラー色褪せ・塗装#21085;がれ部分的 飛び石痕部分的 他トリムしわ・すれ・きず部分的		A キズ U ヘコみサシ B キズヘコみ P 色あせサシ Q ガラスキズ W 腐蝕部 S サビ C 腐食 X 交換部 XX 交換済 登録No. 熊谷 301 ふ 3679 名義中 月 日 までに名義できる方 車体番号 GT7-077782		
FW ①②③	フレ ④⑤	小 ⑥⑦	ホイール ⑧⑨	エアロ シリアル No.
内装 ⑩⑪	シシ ヤブレ	コガ	コガス	オーディオス ⑫⑬
全長 446 cm	幅 180 cm	高さ 159 cm	最大積載量 0 kg	