

2018 Suzuki Every Van PA		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HBD-DA17V	DISPLACEMENT 658 cc		
YEAR / REG. 2018/09	MILEAGE 104,720 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. DA17V-336142	DIMENSIONS (L X W X H) 340 × 148 × 190 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Document delivery takes about 10 days after contract. Steering wheel wear, floor carpet burn hole, interior dirt, cargo area scratches/dirt/mat tears, dashboard scratches, right front fender bent/misaligned.			

初年度登録	メーカー スズキ	ドア枚数 5	排気量cc 軽四	評価点								
H30 / 9月	車名 エブリイ	グレード PA	駆動方式 4WD	4								
車種 自家用・その他()	排気量 660 CC	型式 HBD-DA17V	送付形式	内装 A・B・C								
車検 - - - 年 - - 月 - - 日	燃料 ガソリン	ディーゼル ハイブリッド ()	償目通り品 (保証書・取扱説明書等)									
走行 口内にマークを記入(金・交換・事故・修理・盗難) [] 万 千 百 十 円 [] マイル 1 0 4 , 7 2 0 AT												
外装色 ホワイト カラーNo.	エンジン Qd・AAD・WAG・()	新着商品のO印を記入										
() 名乗者は10万円以上(任意)の加入	内装色	標準装備	Pd PW A1 サンプル 革シート	革シート								
ハンドル 左・右	輸入国	ディーラー	走行	リサイクル料								
セールスポイント		8,400円・税別										
検査記入欄		修復歴										
書類送付は成約後10日前厳かかります。 ハンドルスレ フロアカーペットコグ欠 室内汚れ 荷重キズ・汚れ・マットキレ ダッシュボードキズ 右ドアフェンダー曲がり・ズレ有		有・無										
FW		A	KZ	U	ヘミオオバシ	B	KZ	ヘミオ	P	色あせ・ボケ	G	ガラスキズ
W		修補痕	S	サビ	C	腐食	X	交換済	XX	交換済		
登録地		名義人										
車体番号		月 日 までに名義できる										
FA		DA17V-336142										
FW		A	KZ	U	ヘミオオバシ	B	KZ	ヘミオ	P	色あせ・ボケ	G	ガラスキズ
W		修補痕	S	サビ	C	腐食	X	交換済	XX	交換済		
登録地		名義人										
車体番号		月 日 までに名義できる										
FA		DA17V-336142										
FW		A	KZ	U	ヘミオオバシ	B	KZ	ヘミオ	P	色あせ・ボケ	G	ガラスキズ
W		修補痕	S	サビ	C	腐食	X	交換済	XX	交換済		
登録地		名義人										
車体番号		月 日 までに名義できる										
FA		DA17V-336142										