

2018 Suzuki Hustler A		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE MR31S	DISPLACEMENT 658 cc		
YEAR / REG. 2018/05	MILEAGE 77,700 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Black		
BODY TYPE Kei			
CHASSIS NO. MR31S-117986	DIMENSIONS (L X W X H) 340 × 148 × 167 cm		
INSPECTOR REPORT			
Front windshield has stone chips, scratches, cracks, and repair marks, requiring attention. Seat has a burn hole. Right front fender stay is bent. Steering wheel has scuffs. Undercarriage shows rust. Interior has scratches, dirt, burn holes, scuffs, tears, and rips. Various minor body imperfections.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成30年 5月	車名・グレード ハスラー A	2WD ・ 4WD	評価点 (3.5)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-MR31S	排気量 660 cc	ドア 5 形状 木
		定員 4人	積載 kg
			外装 内装 C B

車歴 自家用	シフト CVT	セールスポイント (正常に機能するものに限りです)
車検 令和9年 5月 (日)	冷房 AC	キーレス☆ETC
走行 7万7千700 km	燃料 ガソリン	
色 ブラック	色替 色コード ZJ3	
R券 8,400 円		装備品 (純正品に限り○をつけてください)
		PS PW ABS EAB AW
		SR ナビ TV カワ
		新車保証書 後日品
		有・無

注意事項申告欄	
Fガラス飛石	
シート焦げ穴	
右Fフェンダーステー重	
ハンドルスレ	
下回りS	
各AU	
フロントガラス	キズ・飛石・ヒビ割・リペア跡・X要
内装	キズ・汚れ・コゲ・穴・スレ・キレ・破レ
車台番号	117986
登録番号	名変中

A-キズ	E-エクボ	U-凹み	W-補修跡	S-サビ	C-腐食	XX-交換済
型式指定番号 登録	類別区分番号 登録					
車庫証明用 登録	長さ	幅	高さ			
	0.00	0.00	0.00			