

2018 Suzuki Hustler A		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
MR31S	658 cc		
YEAR / REG.	MILEAGE		
2018/07	74,167 km		
DOORS	SEATS		
5	4		
TRANSMISSION	FUEL		
AT	Petrol		
STEERING	EXTERIOR COLOR		
Right	Silver		
BODY TYPE			
Kei			
CHASSIS NO.	DIMENSIONS (L X W X H)		
MR31S-118650	340 × 148 × 167 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Whitening on unpainted resin parts, slight wear on driver's seat, minor A-grade damage on door trim, minor A-grade damage on steering column cover, missing rear headrest, cloudy headlights.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H30/7月	メーカー スズキ 車名 ハスラー	ドア枚数 5	ボディ形状 軽四	評価点 4
車種 自家用・その他 ()	排気量 660 CC	型式 MR31S	通称 軽四	内装 A・B・C
車検 9年7月	燃料 ガソリン	ディーゼル	検出通り品 (保証書・取扱説明書 等)	
走行 74,167 km	シフト インパネ	AT		
外装色 スチールシルバーメタリック	カラーNo. ()	エアコン Qb・AAG・WAG・()	装備品のみ O印 を記入	
()	内装色 ()	乗車定員 4人	PS	AW
左・右 左・右	ディーラー・並行	8,400円・預託金	エアロック	TV
セールスポイント CD/横滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/ABS/メモリーナビ他/ミュージックプレイヤー接続可				
検査記入欄 車体塗装面腐食白化 運転席へたり小 ドア内張りA小 コラムカバーA リアヘッドレスト欠品 ヘッドライトくもり		修復歴 有・無 A キズ U ヘコみサレ B キズ・ヘコミ P 色あせ・ボケ Q ガラスキズ W 補修跡 S サビ C 腐食 X 交換済 XX 交換済 登録No. 月 日 までにも名実できる方 車体番号 MR31S-118650 シリアルNo. FW トビキ 内装 3コル シス ヤブレ コガ コガ穴 オーディオ穴		
FW トビキ 内装 3コル シス ヤブレ コガ コガ穴 オーディオ穴		長さ 幅 高さ 最大積載量 cm cm cm Kg		