

|                                                                                                                                                                                                                        |                                              |               |               |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|---------------|---------------|
| 2018 Suzuki XBEE Hybrid MX                                                                                                                                                                                             |                                              | OVERALL<br>4  |               |
|                                                                                                                                                                                                                        |                                              | EXTERIOR<br>- | INTERIOR<br>- |
| MODEL CODE<br>MN71S                                                                                                                                                                                                    | DISPLACEMENT<br>996 cc                       |               |               |
| YEAR / REG.<br>2018/03                                                                                                                                                                                                 | MILEAGE<br>102,200 km                        |               |               |
| DOORS<br>5                                                                                                                                                                                                             | SEATS<br>5                                   |               |               |
| DRIVETRAIN<br>4WD                                                                                                                                                                                                      | TRANSMISSION<br>AT                           |               |               |
| FUEL<br>Hybrid (Petrol)                                                                                                                                                                                                | STEERING<br>Right                            |               |               |
| EXTERIOR COLOR<br>Brown                                                                                                                                                                                                | BODY TYPE<br>SUV                             |               |               |
| CHASSIS NO.<br>MN71S-102657                                                                                                                                                                                            | DIMENSIONS (L X W X H)<br>376 × 167 × 171 cm |               |               |
| SALES POINTS                                                                                                                                                                                                           |                                              |               |               |
| Alloy Wheels                                                                                                                                                                                                           |                                              | 360° Camera   |               |
| INSPECTOR REPORT                                                                                                                                                                                                       |                                              |               |               |
| Exterior: Noticeable scratches and dents have been repaired, but minor scratches and dents remain.<br>Interior: Some noticeable stains are present in parts. Repair history: No abnormalities in the frame components. |                                              |               |               |

[illegible]