

2018 Suzuki XBEE Hybrid MZ with 360° Camera Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-MN71S	DISPLACEMENT 996 cc		
YEAR / REG. 2018/11	MILEAGE 43,870 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. MN71S-128239	DIMENSIONS (L X W X H) 376 × 167 × 171 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			

初年度登録		メーカー		トヨタ株式会社		5		SUV/クワカン		評価点																																											
H30 / 11月		車名 スズキ クロスビー		グレード ハイブリッドMZ 全方位モニター用カメラパッケージ装着車		駆動区分 2WD		4WD		4.5																																											
車種 自動車・その他 ()		排気量 1000 CC		型式 DAA-MN71S		通称形式		内装		A (B)・C																																											
車検 9年11月 / 抹消		燃料 ガソリン		ディーゼル		後日送り品 (保証書・取付説明書 等)																																															
走行 43,870 マイル		インパネ AT																																																			
外装色 パール		カラー-No. (ZVR)		エアコン AC・暖房・WAG・()		装着品のみの O 印 を記入																																															
()		内装色		乗車定員 5 人		(B) (F) (A) サンルーフ		革シート		革シート																																											
左・(B) ディーラー・走行		リサイクル料		4,750円・税別		エアコン (B) ナビ (T) (S)																																															
セールスポイント																																																					
8インチ純正ナビTV/全方位モニター																																																					
特記事項																																																					
ソコラセレクト岸和田【大阪府岸和田市】																																																					
検査記入欄																																																					
<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>ヘコみ/サレ</td> <td>B</td> <td>キズ・ヘコ</td> <td>P</td> <td>色あせ・汚れ</td> <td>G</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>腐蝕跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XL</td> <td>交換済</td> </tr> <tr> <td colspan="2">乗車年</td> <td colspan="2">乗</td> <td colspan="2">500</td> <td colspan="2">ね</td> <td colspan="2">3985</td> </tr> <tr> <td colspan="2">車検番号</td> <td colspan="10">MN71S-128239</td> </tr> </table>												A	キズ	U	ヘコみ/サレ	B	キズ・ヘコ	P	色あせ・汚れ	G	ガラスキズ	W	腐蝕跡	S	サビ	C	腐食	X	交換済	XL	交換済	乗車年		乗		500		ね		3985		車検番号		MN71S-128239									
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコ	P	色あせ・汚れ	G	ガラスキズ																																												
W	腐蝕跡	S	サビ	C	腐食	X	交換済	XL	交換済																																												
乗車年		乗		500		ね		3985																																													
車検番号		MN71S-128239																																																			
<table border="1"> <tr> <td>FW</td> <td>トビ石</td> <td>備A</td> <td>ワレ</td> <td>外装</td> <td>小</td> <td>ホイ</td> <td>エアロ</td> <td>シリアル No.</td> </tr> <tr> <td>内装</td> <td>ヨゴレ</td> <td>シミ</td> <td>ヤブレ</td> <td>コゲ</td> <td>コゲ穴</td> <td>オー・デ・イ</td> <td>スレ</td> <td>車検</td> </tr> </table>												FW	トビ石	備A	ワレ	外装	小	ホイ	エアロ	シリアル No.	内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オー・デ・イ	スレ	車検																								
FW	トビ石	備A	ワレ	外装	小	ホイ	エアロ	シリアル No.																																													
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オー・デ・イ	スレ	車検																																													