

2018 Toyota Noah Si Double Bee		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ZRR80W	DISPLACEMENT 1,986 cc		
YEAR / REG. 2018/02	MILEAGE 52,174 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Minivan		
CHASSIS NO. ZRR80-0398787	DIMENSIONS (L X W X H) 471 × 174 × 183 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Power Sliding Doors (Both Sides) (Both... Cruise Control	
INSPECTOR REPORT			
Exterior: Major scratches and dents have been repaired, but minor scratches and dents remain. Interior: Some noticeable dirt and stains are present. History of repairs: No abnormalities in the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青森県内のカー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

年式登録 H30 2月	メーカー トヨタ ノア	ドア数 5	ボディ形状 ミニバン/ワンボックス	評価点 4.5
車種 自用車	右	ZRR80W	2000	ガソリン
年 9年2月	抹消	52,174	マイル	AC
外装 ブラックシグマアガハガラスフレック	カラーNo.	リサイクル料	12,470円	車台番号 ZRR80-0398787
()	シフト インパネ	AT	乗車定員 7人	長さ cm

車検返却日
(保証書・取説説明書等)

整備
エンジン
変速機
サスペンション
ブレーキ

セールスポイント
3列シートフルフラットワークスルーロード
折りたたみ式5人用ベッド
後部座席スライドアウト
リア・中・前座席エアバック
安全ボディー
安全ボディー
安全ボディー

査定員記入欄

※ダメージレベルに関する注意事項
ダメージレベルは、車体の損傷状況を表す指標です。ダメージレベルが大きいほど、車体の損傷が大きいことを示します。ダメージレベルは、車体の損傷状況を表す指標です。ダメージレベルが大きいほど、車体の損傷が大きいことを示します。

クオリティグレード説明
外装: 劣化による塗装剥離や錆び、小さな凹みや傷が目立ちます。
内装: 劣化による汚れや、部分的な損傷があります。

修理歴: 骨格部分に異常はありません。

車両状態の図解

車両状態の図解は、停止状態で撮影された写真に基づいて作成されています。