

2018 Toyota Passo Moda S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-M700A	996 cc		
YEAR / REG.	MILEAGE		
2018/07	47,674 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Green	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M700A-0114272	366 × 167 × 153 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Navigation System			
INSPECTOR REPORT			
Light dirt inside the cabin, missing armrest lid			

ORIGINAL JAPANESE AUCTION SHEET

H30/7月		トヨタ		5		コンパクトハッチバック		4																					
パスン		モーダ S		4WD																									
車種	白銀用・その他	排気量	1000 CC	型式	DBA-M700A	通称		内装	A・③・C																				
年式	9年7月	抹消		燃料	ガソリン	ディーゼル		後付選り品（保証書・取扱説明書等）																					
走行	47,674 km	インパネ	AT																										
外装色	グリーンII	カラーNo.	XE3	エアコン	AG・AG・WAG	装備品のみ O印 を記入																							
内装色		乗車定員	5人	AW	サンルーフ	革シート																							
左・前・後	ディーラー	走行	リサイクル料	8,190円	エブリック	③	②	④	⑤																				
セールスポイント																													
★スマートアシスト★純正ナビ★地デジTV★バックカメラ★スマートキー★プッシュスタート★ブラックレザー調シートカバー★アームレスト蓋★アイドリングストップ★LEDヘッドライト★ETC★ステアリングスイッチ★					修復歴 有・③																								
検査記入欄 ルーム内薄汚れ アームレスト蓋欠					<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ・サレ</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・サレ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換品</td><td>XX</td><td>交換時</td> </tr> </table>					A	キズ	U	ヘコミ・サレ	B	キズ・ヘコミ	P	色あせ・サレ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換時
A	キズ	U	ヘコミ・サレ	B	キズ・ヘコミ	P	色あせ・サレ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換時																				
登録No.					名義中																								
車体番号					M700A-0114272																								
FW	③	④	⑤	⑥	⑦	⑧	⑨	⑩	⑪																				
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ欠	スレ	車輪	傷																				