

2018 Toyota Passo X L Package S		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
M700A	996 cc		
YEAR / REG.	MILEAGE		
2018/10	41,456 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M700A-1008891	365 × 167 × 153 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Exterior: Major scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains and dirt are present in parts. Repair History: No structural damage.			

車種内の「格」鑑定/JAAA鑑定証の評価と下記記載の評価は異なります									
初年度登録 H30 10月	メーカー トヨタ			ドア枚数 5		ボディ形状 コンパクト/ハッチバック		評価点 4.5	
	車名 パッソ			グレード X		LパッケージS			
車種 自家用	型式 右	M700A			排気量 1000	燃料 ガソリン	内装 B		
車検 9年10月 / 抹消	走行 41,456km	100kmリッター燃費(市・郊・混合) 15.0km/L 100kmリッター燃費(市) 15.0km/L 100kmリッター燃費(郊) 15.0km/L			駆動 AC	安全装置 なし			
ブラック		カラー-No.	リサイクル料		車台番号 M700A-1008891				
()		内装色	シフト インパネ AT		乗車定員 5人	長さ cm	幅 cm	高さ cm	
後日送り状 (保証書・取扱説明書等)									
装備 ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿									
セールスポイント									
バックカメラ/ETC機構/防止装置 (ESC)/運転席エアバック/ス マートキ/オートブレーキ/オート/A B S/6スピーカー/バックセグ/V/ 新装塗装/軽減速/ブレーキ/アイドリング ストップ/パンチシート 法定記入欄									
※ダメージレベルに関する注意事項 傷は軽傷のみ 小傷 1 中傷 2 大傷 3 必ず「へこみ」を記入									
クオリティグレード説明 外装: 気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。 内装: 気になる汚れ等が、部分的にあります。 修理歴: 骨格部位に異常はありません。									

車庫内での確認は、正しく実施する必要があります。