

2018 Toyota Probox Van GL		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE NSP160V	DISPLACEMENT 1,329 cc		
YEAR / REG. 2018/08	MILEAGE 93,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Minivan		
CHASSIS NO. NSP160-0037973	DIMENSIONS (L X W X H) 425 × 169 × 153 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Interior dirt and scratches, steering wheel scuffs, carpet scuffs and tears, seat stains, door mirror scratches, and cargo area scratches and dirt.			

ORIGINAL JAPANESE AUCTION SHEET

H30/8月		メーカー トヨタ		ドア枚数 5	ボディ形状 バン	評価点 4																				
車名 プロボックス GL		グレード		駆動区分 2WD	4WD																					
車種 自家用・その他 ()	排気量 1300 CC	型式 NSP160V	通称形式	内装 A・B・C																						
年 7 月 10 日	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書 等)																							
走行 93,000 km	シフト フロア	AT																								
外装色 ホワイト	カラーNo. ()	エアコン	装備品のみ O印 を記入																							
()	内装色 ()	Qd・AAG・WAG・()	PS	FR	AS	サンルーフ																				
左・右	ディーラー・並行	7,440円・預託金	エブリック	ABS	ナビ	TV																				
セールスポイント																										
検査記入欄			修復歴 有・無																							
AA査定車			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
ルーム内汚れキズ ハンドルすれ カーペットスレ破れ			名義中																							
シートシミ ドアミラー傷 荷室傷汚れ			月 日 までに名義できる方																							
車体番号 NSP160-0037973																										
FW	トピ石	傷A	フレ	外装	小	ホイール	エアロ																			
内装	ゴロ	シ	ヤブ	コガ	コガ穴	オーディ穴	シリアル No.																			
長さ	幅	高さ	最大積重量	Kg																						