


2018 Toyota TANK 1.0 G S		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-M900A	DISPLACEMENT 996 cc		
YEAR / REG. 2018/07	MILEAGE 66,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Brown	BODY TYPE Hatchback		
CHASSIS NO. M900A-0210816	DIMENSIONS (L X W X H) 370 × 167 × 174 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Both... Cruise Control		Pre-Collision Braking	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H30/7月	メーカー トヨタ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4.5
車名 タンク	グレード 1.0 G S 両側パワースライドドア/ETC/オートエアコ	駆動方式 2WD	燃費区分 4WD	
車種 自家用・その他 ()	排気量 1000 CC	型式 DBA-M900A	通称 型式	内装 A・⑨・C
年 -	月 -	日 -	燃料 ガソリン	ディーゼル
走行 66,000 km	シフト インパネ CVT	後日取り込み ()	取付 取付	等 ()
外装色 ブラムブラウクリスタルマイカ	カラーNo. AG・⑨・WAG・ ()	エアコン	AG・⑨・WAG・ ()	整備品のみ O印 を記入
内装色 ()	乗車定員 5 人	⑨	AW	サンルーフ
左・右 左・右	ディーラー 並行	9,130円・預託金	エアロ	ナビ
セールスポイント 側パワースライドドア/ETC/LEDヘッドライト/オーディオ (CD/ラジオ/AUX) /クルーズコントロール/スマートキー/後席ロールサンシェード/オートライト/コーナーセンサー/ステアリングスイッチ/スマートアシスト/オート格納ドアミラー				
検査記入欄	修復歴 有・⑨			
	A キズ U ヘコみ/サレ B キズ・ヘコみ P 色あせ/ボケ Q ガラスキズ			
	W 補修跡 S サビ C 腐食 X 交換品 YX 交換済			
	登録No. 月 日 までに名変できる方			
	名変中			
	M900A-0210816			
FW ⑨	備A	フレ	外装 小	エアロ
内装 ⑨	シミ	ヤブレ	コガ	コガ穴
			オーデ・穴	⑨
車種	重量	寸法	高さ	最大積載量
cm	cm	cm	cm	kg