

2018 Toyota TANK XS		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
M900A	996 cc		
YEAR / REG.	MILEAGE		
2018/06	53,770 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M900A-0195664	370 × 167 × 174 cm		
SALES POINTS			
Pre-Collision Braking			
INSPECTOR REPORT			
Glass: minor scratches (A), needs replacement (X). Interior: medium scratches (B), burn marks, holes, dirt, tears. Steering wheel scuffs, stereo holes. Smart key scratches, minor dents (), no repair history, upper lip damage. Wheel cover A, door mirror A. Underbody lift-up damage (AU). Core support distortion, left front inner panel distortion. Core support bolted (replaced), left front fender stay replaced. Left front C-pillar distortion.			

出品番号	初年度登録年月	車名	ドア	形状	グレード	評価点
	30年6月	タンク 5HB X S				R
車種	車庫用()	型式	DBA-M900A	排気量	1000 CC	定員
車検		年	月	日	フロア AD	MPの取入
走行	+	万	千	百	十	一
	5	3	7	7	0	
外装色	J10-IL		色番号は色番と記入		冷房	MTの取入
内装色	J10-IL		色番号は色番と記入		冷房	MTの取入
外装カラーNo.	4224		輸入車		年・不明	車・並 右・左H
新車保証書	取扱説明書	R券	¥	9,130	名義期限	
後日品	不具合箇所等		ユメテンドラレコ (SSDR)		月 日迄	
注意事項	ユメテンドラレコ (SSDR)		M900A-0195664		月 日迄	
検査員記入	ガラス	④ X要ス	④ コゲ・穴・汚損・破れ	④ コゲ・穴・汚損・破れ		
ハンドルスレ	ステアリング	④ X要ス	④ コゲ・穴・汚損・破れ	④ コゲ・穴・汚損・破れ		
スラッシュ	④ X要ス	④ コゲ・穴・汚損・破れ	④ コゲ・穴・汚損・破れ			
ホイール	④ X要ス	④ コゲ・穴・汚損・破れ	④ コゲ・穴・汚損・破れ			
ドア	④ X要ス	④ コゲ・穴・汚損・破れ	④ コゲ・穴・汚損・破れ			
下回り	④ X要ス	④ コゲ・穴・汚損・破れ	④ コゲ・穴・汚損・破れ			