

2018 Volkswagen VW Polo 5HB TSI Trendline		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE AWCHZ	DISPLACEMENT 999 cc		
YEAR / REG. 2018/12	MILEAGE 35,690 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Hatchback		
CHASSIS NO. WVWZZZAWZJU053945	DIMENSIONS (L X W X H) 406 × 175 × 145 cm		
SALES POINTS			
Pre-Collision Braking			
INSPECTOR REPORT			
Exterior: Major scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains are present. No structural damage.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H30/12月	メーカー フォルクスワーゲン	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 ポロ	グレード TSIトレンドライン			
車種 自家用	ディーラー 右	型式 AWCHZ	排気量 1000	燃料 ガソリン
年 12月	走行 35,690 km	価格 14,040円	車台番号 WVWZZZAWZJU053945	内装 B
外装色 ブラック	カラーNo. ()	リサイクル料 14,040円	車検 AC	重量 Kg
シフト フロア 7 AT	5人	長さ cm	幅 cm	高さ cm

後付品
(保証書・取扱説明書等)

装備
AW サンルーフ
ナビ TV キーレス

セールスポイント
CD機構防止装置(ESC)運転席エアバック/後部座席シートベルトプリクラッシュブレーキ/アイドリングストップ/オートクルーズコントロール

査定員記入欄

※ダメージレベルに関する注意事項
ダメージレベルは1～5で評価されています。1は軽微なダメージ、5は重大なダメージを示します。本車は全体的に良好な状態ですが、一部に軽微なダメージがあります。

クオリティグレード説明
外装: 軽微なダメージや汚れはありますが、全体的に良好な状態です。
内装: 軽微なダメージや汚れはありますが、全体的に良好な状態です。
機械: 正常に動作しています。

車両状態の確認は、必ずしも完全な状態であることを保証するものではありません。