


2018 Volkswagen VW Tiguan TDI 4motion Highline		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-5NDFGF	DISPLACEMENT 1,968 cc		
YEAR / REG. 2018/09	MILEAGE 110,530 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. WVGZZZ5NZJW967553	DIMENSIONS (L X W X H) 450 × 184 × 168 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Adaptive Cruise Control Front Camera Back Camera		Roof Rails Pre-Collision Braking Parking Assist (Auto Steering) Side Camera Navigation System	
INSPECTOR REPORT			
Minor exterior scratches			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H30 9月	メーカー フォルクスワーゲン 車名 ティグアン	ドア数 5	ボディ形状 SUV/クロカン	評価点 4
車種 自家用・その他 ()	排気量 2000 cc	型式 LDA-5NDFGF	駆動方式 4WD	内装 A・⑤・C
車検 - - 年 / 月 / 日	燃料 ガソリン	変速機 ハーフオート (シフト)	後付選用品 (保証書・取扱説明書等)	
走行 110,530 km	マイล์ 530	フロア AT		
外装色 ブラック	カラーNo. ()	エアコン AG・⑤・WAG・()	新着品のみ・①印を記入	
内装色 ()	乗車定員 5人	⑤	サンルーフ	革シート
① 左・② 前・③ 後・④ 右・⑤ 走行	⑥ 17,480円	⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	ABS	TV
セールスポイント Discover Pro ナビゲーション、アラウンドビューカメラ、アダプティブクルーズコントロール、スマートエントリー、LEDヘッドランプ、純正18インチアルミ				
検査記入欄 外装小キズ		修復歴 有・⑥		
		A キズ B ハコボケ C キズ・ヘコ P 色あせ・汚れ Q ガラスキズ W 腐蝕 S サビ C 塗装 X 交換 Y 交換 Z 交換		
		登録月 年 日 名義中		
		月 日 まで名義で販売		
		WVGZZZ5NZJW967553		
① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿