

2018 SUBARU XV 2.0i-S EyeSight 4WD		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-GT7	DISPLACEMENT 1,995 cc		
YEAR / REG. 2018/12	MILEAGE 46,894 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Hatchback		
CHASSIS NO. GT7-190458	DIMENSIONS (L X W X H) 446 × 180 × 159 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Wheel scratches, door mirror scratches, minor exterior scratches and dents (A, U). Interior dirt, scratches, scuffs. Aftermarket wheels. Front glass has scratches, stone chips, cracks, and repair marks (replacement recommended). Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

初年度登録年月 平成 30 年 12 月	車名・グレード XV 2.0i-S7サイト	2WD 4WD	評価点 (4.5)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-GT7	排気量 2000 CC	ドア 5 形状 セダ
定員 5人		積載 8kg	
外装 B		内装 B	

車種 自家用	シフト FAT
年令 令和 9 年 12 月 (日)	冷暖房 AAC
走行 4万 6千 848 km	燃料 ガソリン
色 パール	色コード K1X/T10

R券 11,870 円	セールスポイント (正常に機能するものに限りです) スマートキー☆社外アルミ☆ホイール☆ETC メモリーナビ フルセグTV バックカメラ
--	--

諸商品 (純正品に限り○をつけてください)				
(PS)	(PW)	(BS)	(TB)	AW
SR	ナビ	TV	カメラ	

前車保証書 有・ 無	後日品 スタッドレスタイヤ
---	------------------

フロントガラス 内装 キス・汚レ・ヒビ割・リベア跡・X要 キス・汚レ・コゲ・穴・スレ・キレ・破レ	左 スペア
---	----------

車台番号 190458	登録番号 市川 300 せ 5239
--	---

A・キズ E・コケガ U・23cm W・補修跡 S・サビ C・腐食 XX・交通	型式と定価 446 180	特別定価 1012 159
---	------------------	------------------