

2019 2.0 IS300		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-ASE30	1,998 cc		
YEAR / REG.	MILEAGE		
2019/09	32,045 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ASE30-0006373	468 × 181 × 143 cm		
SALES POINTS			
Alloy Wheels		Adaptive Cruise Control	
Navigation System		Lexus IS Premium Sound System (10 s...	
INSPECTOR REPORT			
Left/right side aero scratches, wheel scratches, minor exterior scratches (A) and dents (U). Shift knob, headliner, trim, steering wheel, and seats show wrinkles/scuffs/scratches. Cargo area and dashboard have scuffs, scratches, and dirt. Front windshield has scratches, stone chips, cracks, and repair marks, requiring replacement. Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和1 9月	車名・グレード IS IS300	2WD 4WD	評価点 (4)
ディーラー・並行 型式 DBA-ASE30	排気量 2000 CC	ドア 4 形状 SD	定員 5人 積載 kg
モデル年式 年 ハンドル 左・右	外装 B	内装 B	
車種 自家用	シフト FAT	セールスポイント (正常に機能するものに限ります)	
車検 年 月 (日)	冷暖 AAC	スマートキー・ETC	
走行 3万2千045 km	燃料 ガソリン	BDRナビ・フルセグ・TV・バックカメラ	
色 ベージュ	色コード 1J7/FB91	諸備品 (純正品に限り○をつけてください)	
R券 11,900 円		(PS) (PW) (BS) (AB) (AW)	
注意事項申告欄		SR ナビ TV カワ	
左右サイドエアロキズ		新車保証書 有・無	後日品
ホイールキズ			
外装小A・小U			
シフトノブスレキズ			
テンパシワスレキズ			
トリムシワスレキズ			
ハンドルスレキズ			
シートシワスレ			
荷室スレキズヨゴレ			
ダッシュスレキズヨゴレ			
フロントガラス (キズ・割れ・ヒビ割れ・リペア跡・X要)			
内装 キズ・汚レ・コゲ・穴・スレ・キレ・破れ			
車台番号 0006373		A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
登録番号		型式認定番号 18143	原付区分番号 0013
		全長 468 cm	全幅 181 cm
		全高 143 cm	