

2019 Audi Audi Q2 30TFSI Sport Assistance Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ABA-GACHZ	DISPLACEMENT 999 cc		
YEAR / REG. 2019/11	MILEAGE 72,621 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. WAUZZZGA8KA087141	DIMENSIONS (L X W X H) 420 × 180 × 150 cm		
SALES POINTS			
Alloy Wheels Navigation System		Pre-Collision Braking	
INSPECTOR REPORT			
Light dirt inside the cabin, exterior P peeling.			

ORIGINAL JAPANESE AUCTION SHEET

R1 / 11月		メーカー アウディ		ドア枚数 5	ボディ形状 SUV/クワカン	年価点 4																				
車名 Q2		グレード 30TFSIスポーツアシスタンスパッケージ		駆動区分 4WD																						
車種 自家用・その他 ()	排気量 1000 CC	型式 ABA-GACHZ	通称記号	内装 A・B・C																						
年 月 日	燃料 ガソリン	ディーゼル	後日選り品 (色選り・取付等)																							
走行 72,621 km	フロア AT																									
外装色 ブラック	カラーNo. AG・AG・WAG・()	装備品のみ O印 を記入																								
内装色	乗車定員 5 人	サンルーフ	革シート																							
左・前・後・側面・走行	15,250円	エアバッグ	ABS	ESP	TV	キーレス																				
セールスポイント ★ワンオーナー★アシスタンスパッケージ★純正ナビ★バックカメラ★TV ★ETC★ACC★パーチャルコックピット★シートヒーター★パワーバックドア★LEDヘッドライト★17インチアルミ★サイドアシスト★アクティブブレンアシスト★パーキングエイド★スマートキー★前後ドライブレコーダ★スペアキー★																										
検査記入欄 ルーム内薄汚れ 外装上Pハゲ																										
<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘッドライト</td><td>B</td><td>キズ・ヘコ</td><td>P</td><td>色あせ・剥け</td><td>G</td><td>ガラスキズ</td></tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換歴</td><td>XX</td><td>交換時</td></tr> </table>							A	キズ	U	ヘッドライト	B	キズ・ヘコ	P	色あせ・剥け	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換時
A	キズ	U	ヘッドライト	B	キズ・ヘコ	P	色あせ・剥け	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換時																	
登録No. 月 日 まで 車体番号 WAUZZZGA8KA087141 シリアルNo.																										
FW	トビ	備A	ワレ	外装	小	ホイール	エアロ																			
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ	スレ																			