


2019 Audi Audi Q3 2.0 TFSI quattro 180PS S line package		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE ABA-8UCULB	DISPLACEMENT 1,984 cc		
YEAR / REG. 2019/06	MILEAGE 33,276 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE SUV		
CHASSIS NO. WAUZZZ8U0JR103616	DIMENSIONS (L X W X H) 440 × 183 × 160 cm		
SALES POINTS			
Alloy Wheels Roof Rails Leather Seats (Sprint Cloth, Leather) Navigation System		Sunroof Power Seats (Front) Back Camera	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 6月	メーカー アウディ	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 Q3	グレード 2.0 TFSI クワトロ 180PS Sラインパッケージ	駆動方式 2WD	燃費区分 49.0	
車種 自動車・その他 ()	排気量 2000 cc	型式 ABA-8UCULB	通称 型式	内装 A・B・C
年式 10年	月 6月	抹消 無し	燃料 ガソリン	ディーゼル
走行 33,276 km	マイル 52,500	フロア	AT	
外装色 ホワイト	カラーNo. LS9R	エアコン AG・BG・WAG・()	後日添付品 (保証書・取扱説明書 等)	
内装色 ()	乗車定員 5人	新着品のみ O印 を記入		
左・右 左・右	輸入区分 デロ	走行 15,640 km	車種 エコ	ボディ A1
セールスポイント 4WD サンルーフ バックモニター 純正ナビ パ ワーバックドア パワーシート シートヒーター パド ルシフト ETC スマートキー				
検査記入欄		修復歴 有・無		
		A 今文 U ヘッドランプ B キズへこみ P 色あせ・サビ Q ガラスキズ W 修理跡 S サビ C 腐食 X 交換品 YX 交換済		
		登録No. 月 日 までに名変せざる方		
		車体 番号 WAUZZZ8U0J R 103616		
内装 トビ石	備A フレ	外装 小 A・U	ホイール A・曲 A・フレ	エアロ シリアル No.
内装 ヨゴレ	シス ヤブレ	コサ コサ	コサ コサ	スレ
長さ 440 cm	幅 183 cm	高さ 159 cm	最大積載量 Kg	