

2019 BMW BMW 5series Touring 523i Touring M Sport Highline Package		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE JL10		DISPLACEMENT 1,998 cc	
YEAR / REG. 2019/09		MILEAGE 64,372 km	
DOORS 5		SEATS 5	
DRIVETRAIN 2WD (FR)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR Black		BODY TYPE Station Wagon	
CHASSIS NO. WBAJL12020BN91464		DIMENSIONS (L X W X H) 495 × 187 × 150 cm	
SALES POINTS			
Alloy Wheels Leather Seats Power Seats (Front) Adaptive Cruise Control Navigation System		Roof Rails Power Tailgate Pre-Collision Braking Back Camera HiFi Speaker System (205W, 12 speakers)	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R1 / 9月	メーカー BMW	ドア数 5	ボディ形状 ステーションワゴン	評価点 4.5
車名 5 シリーズ	グレード 5 23 i ツーリング Mスポーツ ハイラインパッケージ	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 2000 cc	型式 JL10	登録区分 A・B・C	
年 月 日	燃料 ガソリン	ディーゼル	後付選用品 (保証書・取扱説明書等)	
走行 64,372 km	シフト フロア 8 AT			
外装色 ブラック・サファイアメタリック (475)	カラーNo. 475	エアコン AG・AC・WAG ()	新着品のみ O印 を記入	
内装色 ()	乗車定員 5 人		サンルーフ	モーター
左・前・後 左・前・後	走行 22,280 km	燃料消費率 22.280 km	エンジン	エアコン
セールスポイント				
黒レザーシート アクティブクルーズコントロール 純正ナビ TV トップビュー+サイドビューモニター ヘッドアップディスプレイ ドラレコ シートヒーター パワテールゲート LED ETC 純正19AW				
修復歴 有・6				
検査記入欄				
A キズ B へこみ・凹み C 傷・汚れ D 色あせ・変色 E ガラスキズ W 腐食 F サビ G 変色 H 変色 I 変色 J 変色 K 変色 L 変色 M 変色 N 変色 O 変色 P 変色 Q 変色 R 変色 S 変色 T 変色 U 変色 V 変色 W 変色 X 変色 Y 変色 Z 変色				
名義中				
月 日 まで名義中				
WBAJL12020BN91464				
内装 シロ	外装 シロ	小 シロ	大 シロ	エンジン シロ