

2019 BMW BMW X1 sDrive 18i X Line		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE AA15	DISPLACEMENT 1,498 cc		
YEAR / REG. 2019/11	MILEAGE 44,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE SUV		
CHASSIS NO. WBA32AA0405P09221	DIMENSIONS (L X W X H) 446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Pre-Collision Braking Back Camera		Roof Rails Power Seats (Front) Parking Assist (Auto Steering) Navigation System	
INSPECTOR REPORT			
Exterior: Although noticeable scratches and dents have been repaired, small scratches and dents remain. Interior: There are some noticeable stains, etc., in parts. Repair History: There are no abnormalities in the frame components.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録	メーカー	BMW	ドア数	5	ボディ形状	SUV/クロカン	評価点	4
R1 11月	車名	X 1	グレード	sDrive 18i xライ				
車種	自用	ディーラー	右	型式	AA15	1500	ガソリン	B
年	8年	11月	抹消	走行	44,000km	燃費	AC	Kg
外装色	アルビノ・ホワイト(ソリッド・カラー)	カラーNo.	リサイクル料	19,180円	車台番号	WBA32AA0405P09221		
内装色		シフト	AT	乗車定員	5人	長さ	cm	cm

諸口返却
 (保証書・取扱説明書等)

装備
 ◎ サルーフ
 ◎ TV
 ◎ スターレスポイント

セールスポイント
 パワーステアリングカメラ付ナビ付
 駐車アシスト(ESC)機能付ナビ付
 マーキーキーレスエントリー(ABS)付
 手動エアバック付サイドエアバック(HDD)
 ナビ機能付オーディオシステム付
 アダプトドライブモード付

査定員記入欄

ボダージュレベルに関する注意事項
 車体は左記の通り
 車体は左記の通り
 車体は左記の通り

クオリティグレード説明
 外装: 劣化するキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。
 内装: 劣化する汚れ等が、部分的にあります。

車体色: 青枠内に記載されています。

グレー鑑定 コンディションチェックシート
 車台番号: 2020年3月10日
 内装点検
 外装点検
 走行点検
 整備点検
 燃費点検
 安全点検

車両状態の記録
 全車 全車点検済み
 全車 全車点検済み
 全車 全車点検済み

車両状態の記録
 全車 全車点検済み
 全車 全車点検済み
 全車 全車点検済み