

2019 BMW BMW X1 sDrive 18i X Line		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BA-AA15	DISPLACEMENT 1,498 cc		
YEAR / REG. 2019/12	MILEAGE 35,790 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Station Wagon		
CHASSIS NO. WBA32AA0805P47762	DIMENSIONS (L X W X H) 446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels Leather Seats Parking Assist (Auto Steering) Navigation System		Roof Rails Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Light interior stains/scratches, various exterior scratches/dents.			

ORIGINAL JAPANESE AUCTION SHEET

型式		車名		グレード		駆動		排気量(cc)													
1 12		BMW X1		5・W		sDrive 18i xライン		4.5													
型式		排気量		燃料		車種		定員(最大)		積載量(最大)		輸入車									
3BA		AA15		1,500		ガソリン		自家用		5		名		K		車		D車		右H	
ミッション		エアコン		カラー		外装色		PS		PW		17B		ABS		有		内装仕様			
AT		AAC		300		シロ		ナビ		革		7本		7本		有		B			
走行距離		車検		登録ナンバー		注記欄		車台番号		積込金											
35,790		8 12		水戸392ほ 10				WBA32AA0805P47762		19,180		円									
セールスポイント		特記事項・不具合箇所																			
ACC コンフォートアクセス バックカメラ・PDC 半革シート・パワーバックドア LEDヘッドライト・アンビエントラ ETC		内装薄汚れ・スレ 外装各傷・へこみ																			
注意事項																					