

2019 BMW BMW X1 xDrive 18d xLine		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
HT20	1,995 cc		
YEAR / REG.	MILEAGE		
2019/05	24,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBAHT920205L81068	446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Power Tailgate		Pre-Collision Braking	
Parking Assist (Auto Steering)		Back Camera	
Navigation System			
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been repaired, but minor scratches and dents remain. Interior: Some noticeable stains are present in parts. Repair history: No abnormalities in the frame.			

年次登録 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン		評価値 4	
車種 R1/ メーカー BMW 車名 X 1 年次登録 5		車種 SUV/クロカン			