

2019 BMW BMW X1 xDrive 18d xLine		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE LDA-HT20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2019/07	MILEAGE 46,847 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. WBAHT920005L81473	DIMENSIONS (L X W X H) 446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Roof Rails Parking Assist (Auto Steering) Navigation System	
INSPECTOR REPORT			
Mirror A, medium wrinkles on driver's seat, small scuff on door trim, medium pillar trim A, medium scuff on steering wheel, repair marks on right quarter panel, small stone chip on front glass.			

ORIGINAL JAPANESE AUCTION SHEET

R1 / 7月		BMW		5		SUV/クロカン		4	
X 1		xDrive 18d xライン		2WD					
車種: 自家用・その他 ()		排気量: 2000 CC		型式: LDA-HT20		通称: A・B・C			
車検: 年 月 日		燃料: ガソリン		変速機: AT		走行距離: 46,847 km			
走行: 46,847 km		AT							
外装色: Pホワイト		カラーNo.:		5人		PS		PW	
名義: 個人		内装色:		5人		PS		PW	
走行: 46,847 km		AT							
セールスポイント		Fシートヒーター、ATテールゲート、HUD、純正19AW、ACC、LEDヘッドライト、Bカメラ、ETC、マット							
特記事項		不明グリル							
検査記入欄		ミラーA、運転席しわ(中)、ドア内張りすれ(小)、ピラー内張りA(中)、ハンドルすれ(中)、右側修理跡、Fガラス飛び石(小)							
修理履歴		有							
検査項目		A		B		C		D	
検査結果		A		B		C		D	
検査日		2019年7月							
検査場所		WBAHT920005L81473							
検査者		検査者							
検査結果		検査結果							