

2019 BMW BMW X1 xDrive 18d xLine		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-HT20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2019/07	MILEAGE 90,204 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. WBAHT920505N36700	DIMENSIONS (L X W X H) 446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels Leather Seats Parking Assist (Auto Steering) Navigation System		Roof Rails Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Some scratches inside, studless tires, door mirror scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式 R1 / 7月	メーカー BMW	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 X 1	グレード xDrive 18d xライン	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 2000 cc	型式 LDA-HT20	国産 輸入車	内装 A・⑨・C
年 9年	月 2月	走行 90,204 km	変速機 AT	後付選り品 (保証書・取扱説明書等)
外装色 パール	カラーNo. ()	エンジン AG・⑨・WAG・()	安全装置 人	装備品のみ・C印を記入
左・()	右・()	直行 20,540円	ABS	サンルーフ
セールスポイント 純正18インチナビ、ハーフレザー、パワーバックドア、シートヒーター				
検査記入欄 室内一部キズ スタッドレスT ドアミラーキズ				
車体番号 WBAHT920505N36700				
車種 SUV				
車高 cm				