

2019 BMW BMW X1 xDrive 18d xLine		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
LDA-HT20	1,995 cc		
YEAR / REG.	MILEAGE		
2019/09	60,213 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Other	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBAHT920705N82772	446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Pre-Collision Braking		Parking Assist (Auto Steering)	
Back Camera		Navigation System	
INSPECTOR REPORT			
No brake issues, trunk opens/closes smoothly. Seat scuffs, minor child seat marks in rear. Trim grade A. Minor headliner scuffs, light interior dirt. Light exterior grade A. Front windshield stone chip.			

[illegible]