

2019 BMW BMW X1 xDrive 18d xLine Highline Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HT20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2019/09	MILEAGE 21,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR White	BODY TYPE SUV		
CHASSIS NO. WBAHT920705N86949	DIMENSIONS (L X W X H) 446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels Leather Seats Pre-Collision Braking Navigation System		Roof Rails Power Seats (Front) Back Camera	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 9月	メーカー BMW	ドア枚数 5	ボディ形状 SUV/クワカン	評価点 4.5
車名 X 1	グレード xDrive 18d xLine ハイラインパッケージ	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 2000	型式 CC	HT20	内装 A・B・C
年 -	月 -	日 -	登録 2019	走行 21,000
燃料 ガソリン	変速機 オート	駆動方式 フロア 8 AT	後日送り品 ()	新車のみ O印 を記入
外装色 ミネラルホワイト	カラーNo. A00・AAG・WAG・()	エンジン 5人	サンルーフ	ナビ
左・右 左・右	輸入 左・右	走行 20,540	エアコン	TV
セールスポイント				
本革シート/パワーシート/バックカメラ/横滑り防止装置 (ESC)/HID・キセノン・ディスチャージ/運転席エアバック/後部座席エアバック/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/HDDナビ/衝突被害軽減ブレーキ/衝突安全ボディ/4WD/アイドリングストップ/ターボ/シートヒーター/電動リアゲート				
検査記入欄				
修復歴 有・無				
A 今文 U ヘッドランプ B キズへこみ P 色あせ・汚れ Q ガラスキズ W 修理跡 S サビ C 腐食 X 交換品 YX 交換済				
登録No. 月 日 までに名変できる方				
車体番号 WBAHT920705N86949				
内装 トビ石	外装 A	小 A・U	ホイール A・曲	エアロ A・フレ
内装 ヨゴレ	外装 シタ	小 コサ	ホイール コサ	エアロ スレ
長さ cm	幅 cm	高さ cm	最大積載量 Kg	