

2019 BMW BMW X2 xDrive 18d M Sport X		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-YK20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2019/07	MILEAGE 33,868 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Gold	BODY TYPE SUV		
CHASSIS NO. WBAYK720605N17810	DIMENSIONS (L X W X H) 438 × 183 × 154 cm		
SALES POINTS			
Alloy Wheels Parking Assist (Auto Steering) Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 7月	メーカー BMW	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 X 2	グレード xDrive 18d MスポーツX	駆動区分 2WD 4WD		
車種 自家用・その他 ()	積気量 1990 CC	型式 LDA-YK20	選定 型式	内装 A・B・C
車検 - - 年 / 月	燃料 ガソリン ハイブリッド ()	シフト マニュアル	後付選用品 (62 等・取付 等)	
走行 33,868 km	フロア	AT	R3記録簿スベアキー	
外装色 ゴールド	カラーNo. ()	エアコン AG・AG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5 人	サンルーフ	車シート	
左・右 左・右	輸入 区別	走行 18,980円	エレクトロニクス	TV
セールスポイント アドバンスドセーフティPKG/コンフォートPKG/19インチアルミホイール/ドライビングアシスト/パワーバックドア/シートヒーター/ヘッドアップディスプレイ				
検査記入欄 修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 燃費劣化 S ヤビ C 腐食 X 交換部 YX 交換部 登録No. 月 日 家での名実である方 車検番号 WBAYK720605N17810 シリアルNo. FW トボ石 傷A フレ 外装 小 A・U ホイル A・曲 A・フレ 内装 ヨゴレ シシ ヤブレ コガ コガ穴 オーディオ穴 スレ 長さ 437cm 幅 182cm 高さ 153cm 最大積載量 Kg				