

| 2019 BMW X5 xDrive35d M Sport Driving Package                                                                                                                                                                                  |                        | OVERALL                 |          |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------------|----------|
|                                                                                                                                                                                                                                |                        | EXTERIOR                | INTERIOR |
|                                                                                                                                                                                                                                |                        | 4                       |          |
|                                                                                                                                                                                                                                |                        | -                       | -        |
| MODEL CODE                                                                                                                                                                                                                     | DISPLACEMENT           |                         |          |
| 3DA-CV30A                                                                                                                                                                                                                      | 2,992 cc               |                         |          |
| YEAR / REG.                                                                                                                                                                                                                    | MILEAGE                |                         |          |
| 2019/08                                                                                                                                                                                                                        | 66,000 km              |                         |          |
| DOORS                                                                                                                                                                                                                          | SEATS                  |                         |          |
| 5                                                                                                                                                                                                                              | 5                      |                         |          |
| DRIVETRAIN                                                                                                                                                                                                                     | TRANSMISSION           |                         |          |
| 4WD                                                                                                                                                                                                                            | AT                     |                         |          |
| FUEL                                                                                                                                                                                                                           | STEERING               |                         |          |
| Diesel                                                                                                                                                                                                                         | Right                  |                         |          |
| EXTERIOR COLOR                                                                                                                                                                                                                 | BODY TYPE              |                         |          |
| Other                                                                                                                                                                                                                          | SUV                    |                         |          |
| CHASSIS NO.                                                                                                                                                                                                                    | DIMENSIONS (L X W X H) |                         |          |
| WBACV62010LM98719                                                                                                                                                                                                              | 494 × 201 × 177 cm     |                         |          |
| SALES POINTS                                                                                                                                                                                                                   |                        |                         |          |
| Alloy Wheels                                                                                                                                                                                                                   |                        | Sunroof                 |          |
| Roof Rails                                                                                                                                                                                                                     |                        | Leather Seats           |          |
| Power Tailgate                                                                                                                                                                                                                 |                        | Power Seats (Front)     |          |
| Pre-Collision Braking                                                                                                                                                                                                          |                        | Adaptive Cruise Control |          |
| Parking Assist (Auto Steering)                                                                                                                                                                                                 |                        | Front Camera            |          |
| Side Camera                                                                                                                                                                                                                    |                        | Back Camera             |          |
| 360° Camera                                                                                                                                                                                                                    |                        | Navigation System       |          |
| HiFi Surround Speaker System (205W, 1...                                                                                                                                                                                       |                        |                         |          |
| INSPECTOR REPORT                                                                                                                                                                                                               |                        |                         |          |
| Exterior: Noticeable scratches and dents have been repaired, but small scratches and dents remain. Interior: Some noticeable stains are present in parts. Repair History: No abnormalities in the frame/structural components. |                        |                         |          |

[illegible]